

# **DUREMAX®** GPE

## **General Purpose Epoxy Coating**

**PC 255** 

- FEATURES EXCELLENT RESISTANCE TO HOT WATER IMMERSION (80°C)
  - EASE OF APPLICATION SPRAY, BRUSH, ROLLER
  - RANGE OF HARDENERS FOR VARYING CLIMATIC CONDITIONS
  - POTABLE WATER APPROVAL
  - GOOD ABRASION RESISTANCE
  - WIDE RANGE OF COLOURS AVAILABLE FROM THE COLORFAST TINT SYSTEM

USES DUREMAX® GPE is a high performance protective coating locally developed especially for Australia and New Zealand conditions. It is formulated for the protection of structures exposed to severe environments such as chemical plants, offshore platforms, refineries, shiploaders, coal wash plants etc. Untinted DUREMAX® GPE is suitable for fresh and salt-water immersion. DUREMAX® GPE is suitable for use on steel, galvanising and concrete, is compatible over inorganic zinc and epoxy primers, and can be topcoated with a wide range of coating

- SPECIFICATIONS AS/NZS 4020:2018 compliant for use in potable water when used in conjunction with a certified coating system.
  - Certificate of test to AS/NZS 1530.3:1999 available for specific coating system and substrates.
  - APAS 2973 assessed & confirmed to meet all requirements on specific certified products.
  - APAS 2973F assessed & confirmed to meet all requirements on specific certified products.
  - APAS 2973S assessed & confirmed to meet all requirements on specific certified products.

Refer to a Dulux Protective Coatings Consultant for details of the system.

#### **RESISTANCE GUIDE**

WEATHERABILITY	Will yellow with time and chalk on exterior exposure. Neither yellowing nor chalking detracts from the protective properties of the coating. Use a weatherable topcoat if required for appearance.		Resists splash and spillage of most hydrocarbon solvents, refined petroleum products and most common alcohols
HEAT RESISTANCE	Up to 120°C dry heat. Up to 80°C in immersion (White with Fast Cure Hardener)		Excellent resistance to immersion in fresh and saltwater
SALTS	Excellent resistance to neutral and alkali salts	ALKALIS	Suitable for splash and spillage of strong alkali
ACIDS	Suitable for splash and spillage of mild acids	ABRASION	Good when fully cured

### TYPICAL PROPERTIES AND APPLICATION DATA (STANDARD HARDENER)

CLASSIFICATION	General pur	pose epoxy coating	APPLICATION COND	ITIONS		_
FINISH	Semi-Gloss			Min	Max	
COLOUR		k, Light Grey, a full range of	Air Temp.	10°C	40°C	
	tinted colour	rs and MTO factory-made	Substrate Temp.	10°C	40°C	
	colours.		Relative Humidity		85%	
COMPONENTS	Two		Concrete Moisture		<6%	
VOLUME SOLIDS	71%±2					
VOC LEVEL	<330 g/L		<b>COATING THICKNES</b>	S (MICRONS	<b>S</b> )	
FLASH POINT	4°C			Min	Max	Recommended
POT LIFE	3-4 Hours (4	1L, 25°C)	Wet film per coat (µm)	145	45 285 180	
MIXING RATIO V/V	Part A:4	Part B: 1	Dry film per coat (µm)	100	200	125
THINNER	920-08925	Dulux® Epoxy Thinner				
THINNER	920-81942		SUITABLE			pared concrete,
		Thinner	SUBSTRATES	aluminium and	d galvanis	ed steel
PRODUCT CODE	780-63001 780-63002 780-63003 780-38678		PRIMERS	Dulux <sup>®</sup> two pa	ck zinc ric	ch primers
	780-50585 976-84577	Black Standard Hardener	TOPCOATS	Dulux® two pa	ck topcoa	ts
		Fast Cure Hardener Quickturn® Hardener	APPLICATION METHODS	Conventional, assisted spray		spray or air-

### DRYING CHARACTERISTICS AT 125 µm DRY FILM THICKNESS\* (STANDARD HARDENER)

					OVER	COAT
Temperature	Humidity	Touch	Handle	Full Cure	Min	Max <sup>1</sup>
10° C	50%	16 Hours	28 Hours	7 Days	28 Hours	4 Weeks
15° C	50%	12 Hours	20 Hours	7 Days	20 Hours	4 Weeks
25° C	50%	4 Hours	10 Hours	7 Days	8 Hours	4 Weeks

<sup>\*</sup>These figures are a guide only, as ventilation, film thickness, humidity, thinning and other factors will influence the rate of drying.

If the maximum overcoat interval is exceeded then the surface MUST be abraded to ensure maximum intercoat adhesion.

#### SPREADING RATE

with Standard Hardener assuming no losses

### 5.7 square metres per litre equals 125 µm dry film thickness

NOTE: Practical spreading rates will vary depending on such factors as application method, ambient conditions and surface porosity and roughness.

## $\mathsf{DUREMAX}^{ ext{ iny R}}$

### **FAST CURE HARDENER**

#### **COATING THICKNESS (MICRONS)**

#### **APPLICATION CONDITIONS**

	- 1	- /				
	Min	Max	Recommended		Min	Max
Wet film per coat (µm)	135	270	170	Air Temperature	5°C	40°C
Dry film per coat (µm)	100	200	125	Substrate Surface Temperature	5°C	40°C
	•			Relative Humidity		85%
SOLIDS BY VOLUME	75±2%			Concrete Moisture Content		<6%
VOC LEVEL	<300 g/L			·		
FI ASH POINT	>23°C					

POT LIFE 2 Hours (4 litre kit, 25°C)

### DRYING CHARACTERISTICS AT 125 µm DRY FILM THICKNESS\* (FAST CURE HARDENER)

					OVERO	COAT
Temperature	Humidity	Touch	Handle	Full Cure	Min	Max <sup>1</sup>
5° C	50%	9 Hours	18 Hours	7 Days	18 Hours	4 Weeks
10° C	50%	6 Hours	14 Hours	7 Days	14 Hours	4 Weeks
15° C	50%	5 Hours	10 Hours	7 Days	10 Hours	4 Weeks
25° C	50%	2.5 Hours	6 Hours	7 Days	6 Hours	4 Weeks

<sup>\*</sup>These figures are a guide only, as ventilation, film thickness, humidity, thinning and other factors will influence the rate of drying.

1If the maximum overcoat interval is exceeded then the surface MUST be abraded to ensure maximum intercoat adhesion.

NOTE: Use of fast or low temperature hardeners may result in increased yellowing and a reduction of gloss level.

#### SPREADING RATE

with Fast Cure Hardener assuming no losses

6.0 square metres per litre equals 125  $\mu m$  dry film thickness NOTE: Practical spreading rates will vary depending on such factors as application method, ambient conditions, surface porosity and roughness.

### **QUICKTURN® HARDENER**

#### **COATING THICKNESS (MICRONS)**

#### **APPLICATION CONDITIONS**

	Min	Max	Recommended		Min	Max
Wet film per coat (µm)	140	275	170	Air Temperature	5°C	35°C
Dry film per coat (µm)	100	200	200 125 Substrate Surface Temperature		5°C	35°C
				Relative Humidity		85%
SOLIDS BY VOLUME	74±2%			<b>Concrete Moisture Content</b>		<6%
VOC LEVEL	<310 g/L			·		
FLASH POINT	>23°C					
POT LIFE	90 Minutes	(4 litre kit,	25°C)			

### DRYING CHARACTERISTICS AT 125 µm DRY FILM THICKNESS\* (QUICKTURN® HARDENER)

					OVERO	COAT
Temperature	Humidity	Touch	Handle	Full Cure	Min	Max <sup>1</sup>
5° C	50%	7 Hours	14 Hours	7 Days	14 Hours	4 Weeks
10° C	50%	5 Hours	9 Hours	7 Days	9 Hours	4 Weeks
15° C	50%	3 Hours	5 Hours	7 Days	5 Hours	4 Weeks
25° C	50%	90 Minutes	3 Hours	7 Days	3 Hours	4 Weeks

<sup>\*</sup>These figures are a guide only, as ventilation, film thickness, humidity, thinning and other factors will influence the rate of drying.

PC 255 April 2024 Page 2 of 5

<sup>&</sup>lt;sup>1</sup>NOTE: Figures shown are for non-immersion conditions. When used for immersion conditions the maximum overcoat interval is 3 days. The coating MUST be fully cured and completely solvent free prior to being placed under immersion conditions. Refer to the PRECAUTIONS section.

If the maximum overcoat interval is exceeded then the surface MUST be abraded to ensure maximum intercoat adhesion.

<sup>&</sup>lt;sup>1</sup>NOTE: Figures shown are for non-immersion conditions. When used for immersion conditions the maximum overcoat interval is 3 days. The coating MUST be fully cured and completely solvent free prior to being placed under immersion conditions. Refer to the PRECAUTIONS section.

The use of fast or low temperature hardeners may result in increased yellowing and a reduction of gloss level.

SPREADING RATE with Quickturn® Hardener assuming no losses

5.8 square metres per litre equals 125 µm dry film thickness
NOTE: Practical spreading rates will vary depending on such factors as application method, ambient conditions and surface porosity and roughness.



## **DUREMAX® GPE**

#### **TYPICAL SYSTEMS**

This is a guide only and not to be used as a specification. Your specific project needs must be discussed with a Dulux Protective Coatings Consultant.

SURFACE	ENVIRONMENT	PREPARATION GUIDE	SYSTEM		DFT (µm)
STEEL - NEW OR MAINTENANCE	Immersion System EHB7	Abrasive blast clean AS1627.4 Class 3.0	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat	Duremax® GPE (untinted only) Duremax® GPE (untinted only)	150 μm 150 μm
STEEL – NEW	Very high corrosivity (AS2312.1 Cat C5) System PUR 5	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat 3 <sup>rd</sup> Coat	Zincanode <sup>®</sup> 402 Duremax <sup>®</sup> GPE Weathermax <sup>®</sup> HBR	75 μm 200 μm 100 μm
STEEL – NEW	Very high corrosivity (AS2312.1 Cat C5) System PUR5	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat 3 <sup>rd</sup> Coat	Durezinc <sup>®</sup> i90 Duremax <sup>®</sup> GPE Luxathane <sup>®</sup> HPX	75 μm 200 μm 50 μm
STEEL – NEW	High corrosivity (AS2312.1 Cat C5) System PUR 4	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat 3 <sup>rd</sup> Coat	Zincanode <sup>®</sup> 402 Duremax <sup>®</sup> GPE Luxathane <sup>®</sup> HPX	75 μm 125 μm 50 μm
STEEL – NEW	High corrosivity (AS2312.1 Cat C4) Exceeds System PUR3	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat 3 <sup>rd</sup> Coat 4 <sup>th</sup> Coat	Durepon® EZP Duremax® GPE Quantum® FX Quantum® Clearcoat	75 μm 125 μm 55 μm 45 μm
STEEL – NEW	Interior	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat	Duremax® GPE ZP Duremax® GPE	125 μm 125 μm
STEEL – NEW	Interior	Abrasive blast clean AS1627.4 Class 2.5	1 <sup>st</sup> Coat	Duremax® GPE	125 – 200 µm
CONCRETE	Interior	Remove release agents and other surface contaminants	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat	Duremax® GPE (Thin 10-15%) Duremax® GPE	125 μm 125 μm
GALVANISED STEEL, ALUMINIUM	Exterior/Interior	Clean, degrease and abrade or whip blast surface	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat	Duremax <sup>®</sup> GPE Weathermax <sup>®</sup> HBR	150 μm 100 μm

NOTE: If the application is by brush or roller, additional coats will be necessary to achieve the minimum DFT and full opacity

## SURFACE PREPARATION

**Steel**: Round off all rough welds, sharp edges and remove weld spatter. Remove grease, oil and other contaminants in accordance with AS1627.1. Degrease with Gamlen CA 1 (a free-rinsing, alkaline detergent) according to the manufacturer's written instructions and all safety warnings. Abrasive blast clean to a minimum of AS1627.4 Class 2.5.

Immersed steel: Abrasive blast cleaned to AS1627.4 Class 3. Remove all dust by brushing or vacuum cleaning. Steel where abrasive blast cleaning is not viable: Rust, mill scale, oxide deposits and old paint films on metal surfaces must be removed by power tool cleaning according to AS1627.2. Coating performance is proportional to the degree of surface preparation.

**Galvanised steel**: Round off all rough welds, sharp edges, and zinc dags and remove weld spatter. Remove grease, oil and other contaminants in accordance with AS1627.1. Whip blast, taking care not to damage the galvanising layer. Remove all dust by vacuum cleaning.

**Concrete**: Concrete must be at least 28 days old before coating. Remove all laitance, form release, curing compounds, oil, grease and other surface contaminants. Fill any large cracks or voids using Luxepoxy® Filler.

#### **APPLICATION**

Mix each pack thoroughly using a power mixer until the contents are uniform. Ensure bases have been tinted to the correct colour before use. DULUX ASSUMES NO RESPONSIBILITY FOR THE APPLICATION OF INCORRECT COLOUR. Mix the contents of both packs together thoroughly using a power mixer and let stand for 10 minutes. Box all containers before use to ensure colour consistency. Remix thoroughly before application.

#### **BRUSH/ROLLER**

Apply even coats of the mixed material to the prepared surface. When brushing and rolling additional coats may be required to attain the specified thickness.

#### CONVENTIONAL SPRAY

Typical Set-up

Thinning is not normally required, however a small amount (5% or less by volume) of Dulux® Epoxy Thinner (920-08925) or Duthin® 450 (920-81942) may be used.

20-81942) may be used.

Graco AirPro 1.8mm (239543)

65-100 kPa (10-15 p.s.i.) 380-415 kPa (55-60 p.s.i.)

## AIRLESS SPRAY

Standard airless spray equipment such as Graco Xtreme 45:1 with a fluid tip of 17-21 thou (0.43- 0.53mm) and an air supply capable of delivering 550-690 kPa (80 -100 psi) at the pump. Thinning is not usually required but up to 50ml/litre of Dulux® Epoxy Thinner (920-08925) or Duthin® 450 (920-81942) may be added to aid application.

Pressure at Triton 308:

Pressure at Gun:

## DUREMAX® GPE

PRECAUTIONS This is an industrial product designed for use by experienced Protective Coating applicators. Where conditions may require variation from the recommendations on this Product Data Sheet contact your nearest Dulux® Protective Coatings Consultant for advice prior to painting. Do not apply in conditions outside the parameters stated in this document without the express written consent of Dulux® Protective Coatings Australia. Freshly mixed material must not be added to material that has been mixed for some time. Do not apply at temperatures below 10°C when using the Standard hardener or 5°C when using Fast Cure or Quickturn® Hardener. In cold conditions where a fast thinner is required Duthin® 450 (920-81942). Do not apply at relative humidity above 85% or when the surface is less than 3°C above the dewpoint. When used for immersion conditions the maximum overcoat interval is 3 days. The coating MUST be fully cured and completely solvent free prior to being placed under immersion conditions. For best results in water immersion conditions replace Dulux® Epoxy Thinner (920-08925) with Dulux® CR Reducer (965-63020).

DO NOT USE on galvanised steel when using Fast Cure hardener as delamination can occur.

The use of fast or low temperature hardeners may result in increased yellowing and a reduction of gloss level.

#### **CLEAN UP**

Clean all equipment with Dulux® Epoxy Thinner (920-08925) or Duthin® 450 (920-81942) immediately after use.

#### **OVERCOATING**

Degrease with Gamlen CA 1 according to the datasheet. Test adhesion of existing coating by standard cross hatch adhesion test. If the coating fails, remove it. High-pressure water wash at 8.3 to 10.3 MPa (1,200-1,500 p.s.i.) to remove chalk and dust. Abrade surface to provide a good key for the new coating. Epoxies must be abraded if recoated outside the recoat window.

#### **SAFETY PRECAUTIONS**

Read Data Sheet, SAFETY DATA SHEET and any precautions on container labels. SAFETY DATA SHEET is available from Customer Service (13 23 77) or www.duluxprotectivecoatings.com.au

STORAGE

Store as required for a flammable liquid Class 3 in a bunded area under cover. Store in well-ventilated area away from sources of heat or ignition. Keep containers closed at all times.

**HANDLING** 

As with any chemical, ingestion, inhalation and prolonged or repeated skin contact should be avoided by good occupational work practice. Eye protection approved to AS1337 should be worn where there is a risk of splashes entering the eyes. Always wash hands before smoking, eating, drinking or using the toilet.

USING

Use with good ventilation and avoid inhalation of spray mists and fumes. If risk of inhalation of spray mists exists, wear combined organic vapour/particulate respirator. When spraying, users must comply with their respective State Spray Painting Regulations.

FLAMMABILITY

This product is flammable. All sources of ignition must be eliminated in, or near the working area. DO NOT SMOKE. Fight fire with foam, CO<sub>2</sub> or dry chemical powder. On burning will emit toxic fumes.

WELDING Avoid inhalation of fumes if welding surfaces coated with this paint. Grind off coating before welding.

COMPANY INFORMATION		PACKAGING, TRANSPORT AND STORAGE		
Dulux Protective Coatings a division of		PACKAGING	Available in 4 litre and 15 litre packs	
DuluxGroup (Australia) Pty Ltd	DuluxGroup (New Zealand) Pty Ltd	TRANSPORTATION WEIGHT	1.6 kg/litre (Average of components)	
1956 Dandenong Road, Clayton 3168 A.B.N. 67 000 049 427	150 Hutt Park Road, Lower Hutt, NZ A.B.N. 55 133 404 118	DANGEROUS GOODS	Part A: Class 3, UN 1263 Part B: Class 3 UN 2733 (Standard)	

Dulux, Duthin, Duremax, Luxathane, Quantum, Quickturn, Weathermax and Zincanode are registered trademarks of DuluxGroup (Australia) Pty Ltd.

Any advice, recommendation, information, assistance or service provided by Dulux Australia in relation to goods manufactured by it or their use and application is given in good faith and is believed by Dulux to be appropriate and reliable. However, any advice, recommendation, information, assistance or service provided by Dulux is provided without liability or responsibility PROVIDED THAT the foregoing shall not exclude, limit, restrict or modify the right entitlements and remedies conferred upon any person or the liabilities imposed upon Dulux by any condition or warranty implied by Commonwealth, State or Territory Act or ordinance void or prohibiting such exclusion limitation or modification. Products can be expected to perform as indicated in this sheet so long as applications and application procedures are as recommended. Specific advice should be sought from Dulux for application in highly corrosive areas and for large projects to ensure proper performance.