

# APEXIOR® No. 1

## **Coating For Hot Wet Metal Surfaces**

**PC 900** 

- FEATURES THE RECOMMENDED COATING FOR BOILER TUBES AND TIMBER KILNS
  - PERFORMANCE RANGE 95°C TO 370°C
  - SIMPLE ONE PACK SELF PRIMING TOPCOAT

- **BENEFITS** Air dries, easy to apply
  - Single pack
  - Excellent wettability properties surface tolerant
  - Easily recoatable
  - Resistant to boiling water/steam to 370°C
  - · Increases heat transfer efficiency
  - Outstanding resistance to thermal shock (immersion)
  - Inert to water treatment
  - · Prevents corrosion in standby service
  - · Prevents scale buildup

USES APEXIOR® No. 1 is a single component, easy to apply air dry coating specifically formulated for the hot waterside corrosion prevention of metal surfaces. It is a coating that excels in severe thermal

APEXIOR® No. 1 is resistant to continuous immersion in boiling water and steam from 95°C to 370°C. It aids in the reduction and prevention of tight bonding of hard scale and allows for easy cleaning and removal of any scale buildup in steam generating equipment.

APEXIOR® No. 1 prevents pitting corrosion and stops corrosion that has already begun - except for badly pitted areas. It has outstanding wetting properties and adheres well to power tool cleaned

Equipment coated with APEXIOR® No. 1 will also see an increase in heat transfer efficiency. APEXIOR® No. 1 performs ideally with water treatment in steam generating equipment.

Recommended uses for APEXIOR® No. 1 are steam generating equipment, hot condensate return tanks, de-aerators, hot process tanks, autoclaves, sterilizing equipment, mud and steam drums and steam traps.

#### **SPECIFICATIONS**

TYPICAL PROPERTIES AND APPLICATION DATA						
CLASSIFICATION	Boiler coating	APPLICATION CONDITION	APPLICATION CONDITIONS			
FINISH	Matt		Min	Max		
COLOUR	Black	Air Temp.	10°C	50°C		
		Substrate Temp.	10°C	50°C		
		Relative Humidity		50%		
COMPONENTS	One					
VOLUME SOLIDS	34% COATING THICKNESS (MICRONS)					
VOC LEVEL	527 g/L		Min	Max	Recommended	
FLASH POINT	26°C (SDS)	Wet film per coat (µm)	255	300	300	
POT LIFE	Not applicable	Dry film per coat (µm)	87	100	100	
MIXING RATIO V/V	Single Pack					
THINNER	Mineral Turpentine	SUITABLE SUBSTRATES	Abrasive bl		ed, hand ol cleaned steel.	
PRODUCT CODE	230-63079 Apexior No. 1	PRIMERS	Not applica	ble		
'		APPLICATION METHOD	Convention brush	al spray,	airless spray or	

## DRYING CHARACTERISTICS AT 100 µm DRY FILM THICKNESS\*

				OVERCOAT		
Temperature	Humidity	Touch	Full Cure	Min	Max <sup>1</sup>	
21° C	50%	6-8 Hours	7 Days	16 Hours	24 Hours	

<sup>\*</sup>These figures are a guide only, as ventilation, film thickness, humidity, thinning and other factors will influence the rate of drying.

### **SPREADING RATE** ASSUMING NO LOSSES

## 3.4 square metres per litre equals 100 µm dry film thickness

NOTE: Practical spreading rates will vary depending on such factors as application method, ambient conditions, surface porosity and roughness.

<sup>&</sup>lt;sup>1</sup> Allow equipment to air dry for 7 days before placing equipment into service. Coating must be free of solvents prior to being placed into service

## APEXIOR No. 1

### TYPICAL SYSTEMS

This is a guide only and not to be used as a specification. Your specific project needs must be discussed with a Dulux Protective Coatings Consultant.

SURFACE	ENVIRONMENT	PREPARATION GUIDE	SYSTEM		DFT (μm)
STEEL - NEW	Internal	Power tool clean SSPC_SP 11, Level 1 or Abrasive blast AS1627.4 Class 2	1 <sup>st</sup> Coat 2 <sup>nd</sup> Coat	Apexior <sup>®</sup> No 1 Apexior <sup>®</sup> No 1	100 μm 100 μm

## **PREPARATION**

SURFACE To ensure optimum long-term coating system performance, surfaces must be clean, dry and free from dirt, oil, grease, salts, welding flux, mill scale, rust, oxides, old paint, corrosion products or other foreign matter. Remove all surface imperfections that will induce premature coating system failure. Chip or scrape off weld splatter. Grind down sharp and rough edges, gouges, and pits. Abrasive blast surface per specification SSPC-SP 10, "Near-White Blast Cleaning", or per NACE Standard No. 2 to a profile depth of 38 - 50 microns. Abrasive used in blasting should be selected carefully from materials of mesh size required to produce the desired anchor pattern.

If abrasive blasting is not permitted, power tool clean to bare metal according to SSPC\_SP 11, Level 1. Coating performance is proportional to the degree of surface preparation.

### **APPLICATION**

Redisperse any settled-out pigments by stirring with a paint paddle followed by thorough mixing to a uniform consistency with an explosion-proof or air-driven power mixer. Do not open containers until ready to use. Keep lid on container when not in use. Do not apply APEXIOR® No. 1 in heavier films than specified since blistering may occur. During application of APEXIOR® No. 1 ventilate area with high volume of air.

**BRUSH/ROLLER** 

Do not use synthetic bristle brushes. Using the side of the brush, scoop APEXIOR® No. 1 from the container and apply in sweeping strokes, overlapping the brush strokes. Do not attempt to remove brush marks.

CONVENTIONAL SPRAY

Typical Set-up

Thin up to 200ml/litre with mineral turpentine to aid atomisation.

Graco AirPro: 2 18mm 70 - 100 kPa (10 - 15 psi) Pressure at Triton 308: Pressure at gun: 240 - 275 kPa (35 - 40 psi)

**AIRLESS SPRAY** 

Standard airless spray equipment such as a Graco 205-591 with a fluid tip of 163-610, or a Graco 208-663 with a fluid tip of 163-315 and an air supply capable of delivering 550-620 kPa (80-90 p.s.i.) at the pump. Thinning is not normally required but up to 100 ml/litre of mineral turps may be added to aid application.

#### **PRECAUTIONS**

This is an industrial product designed for use by experienced Protective Coating applicators. Do not apply in conditions outside the parameters stated in this document without the written consent of Dulux® Australia. Combustible Liquid and Vapour. Keep away from heat, sparks and flame. Vapours may cause flash fire. Do not breathe vapours or spray mist. Avoid contact with eyes, skin and clothing. Use with adequate ventilation during mixing and application. Wear an appropriate, properly fitted organic vapour cartridge-type respirator (NIOSH approved) during and after application unless air monitoring demonstrates vapour mist levels are below applicable limits. Follow respirator manufacturer's directions for respirator use. Wash thoroughly after handling. Wear protective gloves, chemical safety goggles and impervious protective clothing. Use skin cream. In confined spaces use a positive pressure supplied-air respirator (NIOSH approved). Use explosion-proof lights and electrical equipment. Use only nonsparking tools and equipment. Wear conductive and nonsparking footwear. Make certain all electrical equipment is grounded. Observe all safety precautions and follow procedures described in OSHA regulations. Not recommended for hot water tank service with average operating temperature below 93°C, immersion in solvents or acids, or interior of boilers held for long periods in cold, wet layup or standby service. A water immersion temperature of 93°C must be achieved for the coating system to withstand water temperature below 93°C

## CI FAN UP

Clean all equipment with mineral turpentine immediately after use.

## OVERCOATING **SAFETY**

Power tool clean to remove all rust and scale and then wash to remove surface contamination. The surface must be free of oil, grease and other contaminants.

## **PRECAUTIONS**

Read Data Sheet, SAFETY DATA SHEET and any precautions on container labels. SAFETY DATA SHEET is available from Customer Service (13 23 77) or www.duluxprotectivecoatings.com.au

**STORAGE** 

Store as required for a flammable liquid Class 3 in a bunded area undercover. Store in well-ventilated area away from sources of heat or ignition. Keep containers closed at all times.

**HANDLING** 

As with any chemical, ingestion, inhalation and prolonged or repeated skin contact should be avoided by good occupational work practice. Eye protection approved to AS1337 should be worn where there is a risk of splashes entering the eyes. Always wash hands before smoking, eating, drinking or using the toilet.

**USING** 

Use with good ventilation and avoid inhalation of spray mists and fumes. If risk of inhalation of spray mists exists, wear combined organic vapour/particulate respirator. When spraying, users must comply with their respective State Spray Painting Regulations.

**FLAMMABILITY** 

This product is flammable. All sources of ignition must be eliminated in, or near the working area. DO NOT SMOKE. Fight fire with foam, CO2 or dry chemical powder. On burning will emit toxic fumes.

Avoid inhalation of fumes if welding surfaces coated with this paint. Grind off coating before welding.

COMPANY INFORMATION		PACKAGING, TRANSPO	ORT AND STORAGE
Dulux Protective Coatings is a division of	f	PACKAGING	Available in 3.79 litre containers
DuluxGroup (Australia) Pty Ltd	DuluxGroup (New Zealand) Pty Ltd	TRANSPORTATION WEIGHT	1.09 kg/litre
1956 Dandenong Road, Clayton 3168 A.B.N. 67 000 049 427	150 Hutt Park Road, Lower Hutt, NZ A.B.N. 55 133 404 118	DANGEROUS GOODS	Class 3 UN 1263

Dulux and Apexior are registered trademarks of DuluxGroup (Australia) Pty Ltd.

Any advice, recommendation, information, assistance or service provided by Dulux Australia in relation to goods manufactured by it or their use and application is given in good faith and is believed by Dulux to be appropriate and reliable. However, any advice, recommendation, information, assistance or service provided by Dulux is provided without liability or responsibility PROVIDED THAT the foregoing shall not exclude, limit, restrict or modify the right entitlements and remedies conferred upon any person or the liabilities imposed upon Dulux by any condition or warranty implied by Commonwealth, State or Territory Act or ordinance void or prohibiting such exclusion limitation or modification. Products can be expected to perform as indicated in this sheet so long as applications and application procedures are as recommended. Specific advice should be sought from Dulux for application in highly corrosive areas and for large projects to ensure proper performance.